SOUTH PRODUCTION NOTES

January 9, 2014 Day Shift

BASF EMPLOYEES
48 Last Recordable
193 Last Lost Time



#1 MED Al-5637: On hold until we can get the dust collector issues resolved.(No suction on spiral and bag off area (dust collector #8).

#1 RC / Al 5637: Down/Caustic line is frozen on Trimer.

Day shift: No update

Afternoon Shift: Kirk will need to perform final work on PLC Rack sometime Thursday. Coordinate timing with Kirk before attempting to start #1 or #2 calciners, and confirm with Kirk whether the need to shut down #3 calciner.

Midnight Shift: No change.

Exhaust to F1 when not feeding, then to Trimer only after frozen caustic line is corrected and ready to feed

#2 MED line/ Cu-0602: Auger to be re-installed and correct chiller fault Thursday.

Day Shift: Chiller should be ready...waiting for auger/barrel from maintenance.

Afternoon Shift: Chiller installed but keep getting fault (high refridg pressure). Grodecki and Kaput notified. Also, installed barrel...need to install auger and get ready for batches Thursday.

Midnight Shift: Auger installed. On hold for day shift. Will need to get chiller fault reset.

#2 RC/ cleaned up for Cu-0602: Still down

Day shift: No change

Afternoon Shift: No change. NOTE: Kirk will need to perform final work on PLC Rack sometime Thursday. Coordinate timing with Kirk before attempting to start #1 or #2

calciners, and confirm with Kirk whether the need to shut down #3 calciner.

Midnight Shift: No change. Exhausting to

New Pfaudler / Ni 2458 next: Pfaudler was rinsed for Ni 2458 (need detailed cleaning

instructions from Grodecki, also MOD).

Day shift: Waiting for MOD from Grodecki...should have available Thursday

Afternoon Shift: No change Midnight shift: No change.

Tank 6 / Ni Solution: Tank is clean, rinsed, pump checked, and ready

Day shift: No activity

Afternoon Shift: Tank rinsed, pump checked, lines flushed. Should be ready.

Midnight shift: No change. On hold. Grodecki may want a tank made on Thursday.

National Dryer / Clean for Ni 2458 : Done

Day shift: no change

Afternoon shift: No change Midnight shift: No change.

#4 RC / Cleaning for Ni-2458: System was cleaned and running sand through several

times to flush-out. Need engineer to inspect.

Exhaust to

Day shift: No change. Need to add screens to screener (.156 x 5/16 oversize, 12 mesh fines)

Afternoon Shift: Screens added.

Midnight shift:

#3 MED line / D-1795 NAQ: Extruder/mixer/pulva on hold. Continue feeding D 1795

buggies to dryer through floor.

Day shift: Hold

Afternoon Shift: Continue on Midnight Shift: Continued to run.

#3 RC/ D-1795 NAQ: Will continue to feed.

Exhausting to CTO

Day shift: Waiting for calciner temps to stabilize, then restart feeding.

Afternoon Shift: Continue on. NOTE: Kirk will need to perform final work on PLC Rack

sometime Thursday. Coordinate timing with Kirk before attempting to start #1 or #2

calciners, and confirm with Kirk whether the need to shut down #3 calciner.

Midnight shift: Continued to feed. Calciner kicked out twice during shift.

Abbe Blender / D-5206: We are out of HF solution.

Day shift: No change

Afternoon Shift:

Midnight shift: No change.

PK Blender / OxyVinyl Catoxid next: Blender, solution tank and lines cleaned out.

Floor also cleaned.

Day shift: No change. Waiting for #5 clean-up to be done

Afternoon Shift:

Midnight shift: No change.

#5 RC / OxyVinyl Catoxid next: Down for cleaning

Exhaust to

Day shift: Continued cleaning (calciner, dust collectors). Review and continue during afternoon. 5B dust collector was cleaned out, need to install filters

Afternoon Shift: Filters installed on both DCs. Need to walk through system, clean up old

filters pulled, and make sure everything is closed up.

Midnight shift: Cleaning continued(roton blower/purge air tube/outside of calciner).

Old Pfaudler - D 1795: Continue on.

Day Shift: Pump fixed, restart batches

Afternoon Shift: Continue (Ni nitrate pump repaired)

Midnight shift: Continued on.

Tank 7 / AMT for D-1795 NAQ: Continue...make next tank when getting low

Day shift: Continue monitoring temps and tank level.

Afternoon Shift: Continue monitoring temps and tank level.

Midnight shift: Tank at 28%. Temperature at 30 degrees.

#6 - RC / D-0756: Keep lit for heat in bldg. 27. NOTE: need to keep Sly scrubber water tank filled each shift. Must use garden hose inside HC-11 as city water line currently frozen/blocked. Fill tank, then pull hose back inside HC-11 so it does not freeze.

Exhaust to Sly Scrubber

Day Shift: Keep calciner on for heat in B-27.

Afternoon shift: Keep lit for heat in bldg. 27. NOTE: need to keep Sly scrubber water tank filled each shift. Must use garden hose inside HC-11 as city water line currently frozen/blocked. Fill tank, then pull hose back inside HC-11 so it does not freeze.

Midnight shift: Sly scrubber filled.

Tower 3 / Cu-1986: Loaded and running...had issues with mass spec gas samples.

Work notification was written, Grodecki notified. Mass spec gas sample line was opened up, should be OK.

Tower 6 / E-474: Tower reloaded and running.

Day shift: Will load tower Wednesday afternoon

Afternoon shift: 3 has one more day; 6 loaded and running

Midnight Shift: Tower 3 should be ready to unload late on day shift.

Harrop Kiln - Al-3921 T 3/16": Down...saggers will need to be removed. Also, parts

from the harrop screener were used on TK #2 screener.

Day Shift: No change

Afternoon Shift: No change Midnight Shift: No change.

North Screener / Cu-0860 done, change to Cu 1986:

Day shift: Need to change screener over to Cu 1986, however water lines frozen. Afternoon Shift: No change. Need to take apart but still have no water for washing.

Midnight shift: Both screeners washed down.

South Screener / Cu-0860 done, change to E 474:

Day shift: Need to change screener over to E 474, however water lines frozen.

Afternoon Shift: No change. Need to take apart but still have no water for washing.

Midnight shift: Both screeners washed down.

HC-11 Tanks / Cu 5020: Completed. Maintenance needs to repair or replace tank #6

pump.

Day shift: No change

Afternoon Shift: No change. Midnight shift: No change

#2662 Pill Machine / Al-3917 3/16: Finished. Holding for decision to switch to 3915.

#2664 Pill Machine / Al-3917 3/16: Finished. Holding for decision to switch to 3915.

Tunnel Kiln #2 / BE-0101 Extrusions: Completed.

Day shift:

Afternoon Shift: Midnight shift:

Tunnel Kiln #4 / Cu-0540: Continue loading/unloading

Day shift: Continue

Afternoon Shift: Continue. NOTE: water line over bathroom ruptured. Was cleaned up

but need maintenance to work on repairs.

Midnight shift: No change.